

BRG USB/Serial Port Adapter

Installing the Driver

1. Insert the CD
2. Connect adapter to the USB port
3. The “Found New Hardware Wizard” should appear.
4. Select “Install from a specific location”
5. Check “Search for the best driver in these locations”
6. Then check “Search removable media” and “Include this location in the search”
7. Use the Browse button to locate the appropriate directory on the CD drive. For Windows XP, select “WinXP”

The driver will assign the first available COM port to the USD adapter.

To determine the port assigned,
Open the Control Panel
Select System
Select Hardware
Select Device Manager
Select Ports – The assigned com ports will be displayed

Uninstalling the Driver

For Windows XP, run the program d:\WinXP\DrvRemover.exe (where d = the CD drive)
Select the appropriate directory for other operating systems.